

# Inspection Photos

API: 071-07515

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/2/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-07515 | Date: 9/2/2020

## Inspection Photos



**Photo 1.** Facing northeast toward the location which is fenced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 9/2/2020

## Inspection Photos



**Photo 2.** Facing east toward the location at southern portion. Drill rows are visible indicating the location has been reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 9/2/2020



## Inspection Photos



**Photo 3.** Facing east toward the location at northern portion. Drill rows are visible indicating the location has been reseeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07515 | Date: 9/2/2020