

Inspection Photos

API: 071-08625

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 9/2/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 1. Facing northeast along the access road. Berms have been installed along the road with rock rip/rap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 2. Facing northeast along the access road ascending the hill side. Additional berms have been installed along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 3. The erosion near the culvert has been repaired and a berm has been installed to direct stormwater towards the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 4. Facing west. Areas of erosion have been repaired and additional BMP's are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 5. Facing north along the road. Areas of erosion have been repaired and additional BMP's are installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 6. Facing west along the road traveling to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 7. Facing northwest toward the location. Vegetation has uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 8. Facing southwest at the location. Vegetation has uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020

Inspection Photos



Photo 9. Facing southwest at the location. Vegetation has uniformly established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 9/2/2020