

# Inspection Photos

9/04/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334064

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334064



**Photo 1:** Photo taken from the west end of the Location, facing north. Photos 1-4 provide an overview of the Location from north, northeast, southwest to south.





## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334064



**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334064



**Photo 3:** See comments under photo 3



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334064



**Photo 4:** See comments under photo 1.





Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334064



**Photo 5:** Photo shows the marker for southwestern guy line anchor is in disrepair.

