

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402484142

Date Received:

09/08/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 5 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696201631

Inspection Date: 08/10/2020

FIR Submit Date: 08/11/2020

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335667

Location Name: N PARACHUTE Number: WF15A-23 County: _____
F23596

Qtrqtr: SEnw Sec: 23 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.601606 Longitude: -108.140351

FACILITY - API Number: 05-045- -00 Facility ID: 335667

Facility Name: N PARACHUTE Number: WF15A-23
F23596

Qtrqtr: SEnw Sec: 23 Twp: 5S Range: 96W Meridian: 6

Latitude: 39.601606 Longitude: -108.140351

CORRECTIVE ACTIONS:

2 CA# 141156

Corrective Action:

Date: 08/16/2020

Submit a recalamation plan to address reclamation of the interim areas disturbed, and possibly impacted, during spill response efforts. At a minimum the plan shall include:

- 1) Detailed schedule for reclamation activities
- 2) Methods and depth for decompaction
- 3) Seed mix, and application rates (in PLS/square foot), and application methods
- 4) Mulch type, application rates and application methods
- 5) Fertilizer/soil amendments

Attach plan to a Form 4 Sundry and submit to Reclamation Specialist Trujillo and West Environmental Protection Specialist Arauza.

Response: CA COMPLETED

Date of Completion: 09/02/2020

Operator Comment: Plan was submitted.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 141157

Corrective Action: Collect a minimum of 3 soils samples from below the excavated soil stockpile areas once they have been removed, and a minimum of 3 soil samples from an appropriate adjacent reference area for comparative laboratory analysis of pH, EC and SAR. Attach the soil sample analysis and map of sample locations/depth/etc.. to a Form 4 Sundry and submit to Reclamation Specialist Trujillo and West Environmental Protection Specialist Arauza.

Date: 07/30/2020

Contact Environmental regarding a sampling plan for the excavated materials as soon as possible, no later than 7/30/2020.

Response: CA COMPLETED

Date of Completion: 09/02/2020

Operator Comment: Form 4 was submitted.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 9/8/2020 4:20:21 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

--	--

Total Attach: 0 Files