

Pit Status Evaluation Form

Pit Overview:

Pit Name: DM Kerr	Facility ID: 116359
Current Status: Unknown	Status Date: 09/23/1999
Current Operator: NORAM MINES INC / 63510	
Updated Operator: NORAM MINES INC / 63510	
Form 15 Pit Permit Doc #: 706113	Permit Date: 09/12/1972
Related Facilities:	

County: Logan			
Township: 8N	Range: 54W	Section: 35	QQ: SENW
Original Latitude/ Longitude: 40.618613 / -104.518546			
Updated Latitude/ Longitude: 40.617691 / -103.385773			
Basis for Location Change:			
Original lat/lon autogenerated from incorrect PLSS in 8N64W; revised lat/lon based on pit permit and aerial photos			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 706113 | Date: 09/12/1972 |
| <input type="checkbox"/> | Field Inspection(s) – Doc #: | Date: |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

related wells plugged in 1985/1986

Pit Status Review Summary: