

BP L48 San Juan



V2 Compliance Follow Up Form

18154290860

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20200908-18154290860

V2 Compliance Follow Up Form

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Sep 8, 2020 12:52:42 PM MDT

1600 Holman Canyon Rd, Bayfield, CO 81122, USA

Sep 8, 2020 12:44:04 PM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 27, 2020
Well Name	KAIME FEDERAL GAS UNIT 1
API Number	50670715500
Select State	Colorado
Work type	BLM Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Weed Debris Clean Up Contaminated Soils

Photo of first corrective action completed



Completed work description Corrective
Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Cleaned up stains

Photo of third corrective action completed



Completed work description of corrective action 3

Removed weeds

Photo of fourth corrective action completed



Completed work description

Installed rock run down

Completed work description of corrective action 4

Fixed erosion

Additional photos



Additional photos



Additional photos

**Summary of all work completed**

Compliance, cleaned up stains ,fixed erosion , installed rock run down , removed weeds and picked up trash