

Construction and Stormwater Inspection

August 26, 2020

Operator: NICKEL ROAD OPERATING LLC #10669

Location ID: 460556

Inspection Document #: 697501953

Weld County, CO

NWNW Section 17 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DEHAAN NORTH /PAD
Location ID: 460556



Photo 1. Photo taken from the southern location, facing West. Photo illustrates a ditch and berm BMP has been installed.



Photo 2. Photo taken from the southern location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: DEHAAN NORTH /PAD
Location ID: 460556



Photo 3. Photo taken from the northeastern location, facing West. See comments under Photo 1. Note: the pooled water feature is from cattle operations, not stormwater.



Photo 4. Photo taken from the northeastern location, facing East. See comments under Photo 3.

Inspection Photos
Location Name: DEHAAN NORTH /PAD
Location ID: 460556



Photo 5. Photo taken from the northern location, facing Southwest. Photo illustrates the cut slope and property line boundary.



Photo 6. Photo taken from the entrance of the location off CR 39, facing West. Photo illustrates a vehicle tracking device BMP.