

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2020

Submitted Date:

09/09/2020

Document Number:

698701851

FIELD INSPECTION FORM
 Loc ID 431018 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431014	WELL	PR	05/01/2020	OW	123-36377	NAKAGAWA B13-62-1HN	PR
431016	WELL	PR	09/11/2013	OW	123-36378	NAKAGAWA B13-64-1HN	PR
431019	WELL	PR	09/12/2013	OW	123-36379	NAKAGAWA B13-65-1HN	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 431014 Type: WELL API Number: 123-36377 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 431016 Type: WELL API Number: 123-36378 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 431019 Type: WELL API Number: 123-36379 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On (9/9/2020) at approximately (11:31 HRS), I, Inspector (Abe Serna), Conducted an on-site inspection at (Nakagawa #B13-65-1HN) (Noble Energy), at (Location # 431018) in (Weld County) Colorado. While there, I observed (PR Well) No follow up on this blue inspection needs to be conducted. This is a summary of inspection report.</p>	sernaa	09/09/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698701852	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5242729