

**Inspection Photos**  
**Location Name: Nielson #4**  
**API: 05-007-06117**



**Nielson #4 pump jack and well head.**



**Staining around well head.**

**Inspection Photos**  
**Location Name: Nielson #4**  
**API: 05-007-06117**



**Weeds present within secondary containment berm.**



**Nielson #4 crude oil AST. Weeds present within secondary containment berm.**