

**Inspection Photos**  
**Location Name: Nielson #5**  
**API: 05-007-06141**



**Nielson #5 well head and pump jack. Old sign remains on location.**



**Weeds present near well head and pump jack.**



**Inspection Photos**  
**Location Name: Nielson #5**  
**API: 05-007-06141**



**Well head and surrounding soil are stained and wet.**



**Ensure adequate capacity of secondary containment berm at Nielson #5 tank battery.**