

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2020

Submitted Date:

09/10/2020

Document Number:

699102346

FIELD INSPECTION FORM

Loc ID 336618 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245902	WELL	SI	04/01/2019	GW	123-13697	GEMINI B29-5	PA

General Comment:

[This is a follow up to FIRR # 402483779. CA has been corrected.](#)

Inspected Facilities

Facility ID: 245902 Type: WELL API Number: 123-13697 Status: SI Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 9/10/20 at approximately 0920hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402483779 at Gemini B29-5 of Noble Energy, at Location ID # 336618 in Weld County, Colorado. Weather Conditions: overcast skies & wet During this inspection the compliance issues have been corrected to comply with COGCC rules Form 6(S) has been submitted document # 402461397. See attached photos. This is a summary of inspection report.</p>	burnsa	09/10/2020