

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	300 BBL Crude Oil Tank - NFPA Label, 100 BBL PIT is fading; no longer visible- Capacity Label, see photos		
Corrective Action:	Comply with Rule 210.d.	Date:	10/09/2020
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	<input type="text"/>				

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the other Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares berm with the Crude Oil Tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	500 BBLs	STEEL AST		40.878440,-104.238550
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 464515 Type: Location API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Wells and Tank Battery Shut-In at the time of this Inspection

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine Field Inspection. 300 BBL Crude Oil Tank NFPA Label has faded no longer visible. 100 BBL PIT – Capacity Label</u>	petrie	09/10/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302440	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5244190