

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 335383



New 2" stainless steel dump lines installed at separators

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 335383



New 2" stainless steel dump line riser at tank battery



Old 2" carbon steel flowline abandoned and removed from location