

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 335811



New 2" stainless steel dump lines installed

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 335811



New 2" stainless steel dump line riser at separators



Old 2" carbon steel flowline abandoned and removed from location