

Inspection Photos
Location Name: Shable 1161 30-43
Location ID: 413460



Colorado Oil and Gas Conservation Commission
40.88778, -104.24648, 5021.6ft, 188°
09/09/2020 14:37:51

Photo 1 – Pumping Unit, Weeds



Colorado Oil and Gas Conservation Commission
40.88767, -104.24632, 5052.4ft, 217°
09/09/2020 14:39:40

Photo 2 – Stained Soil inside Engine House