

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2020

Submitted Date:

09/12/2020

Document Number:

696103712

FIELD INSPECTION FORM

Loc ID 306509 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289302	WELL	PA	02/19/2015	GW	123-24808	WAGNER 30-33	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
Well(s): 1: Plugged & Abandoned | PA.
Battery: Active.

Centralized Battery serves 2 Location IDs (306508, 310319).
(Well(s): 1: Producing | PR ; 1: Shut-In | SI).

Centralized Battery formerly served 3 Location IDs (306507, 306509, 306562).
(Well(s): 3: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696103706 and/or Location ID #306508 for Battery / Facility, Equipment info.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Plunger Lift	# 0		
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 289302 Type: WELL API Number: 123-24808 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 09/11/2020 at approximately 11:48 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: WAGNER-67N64W /30SWSW Location ID: 306509 Well Name: Wagner 30-33 API: 05-123-24808 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (306508, 310319). (Well(s): 1: Producing PR ; 1: Shut-In SI).</p> <p>Centralized Battery formerly served 3 Location IDs (306507, 306509, 306562). (Well(s): 3: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696103706 and/or Location ID #306508 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #400808250 indicates plugging, cut/cap date: 02/19/2015. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	09/12/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103713	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5245471