

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402395265

Date Received:

05/11/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Ghan, Scott

Phone

970 876-1959

Email

sghan@grizzlyenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692402118

Inspection Date: 04/22/2020

FIR Submit Date: 04/28/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 417608

Location Name: GGU DALEY Number: 14A-19-691 County: \_\_\_\_\_

Qtrqr: SESW Sec: 19 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.506485 Longitude: -107.599029

FACILITY - API Number: 05-045-00 Facility ID: 417608

Facility Name: GGU DALEY Number: 14A-19-691

Qtrqr: SESW Sec: 19 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.506485 Longitude: -107.599029

CORRECTIVE ACTIONS:

1 ☒ CA# 138435

Corrective Action: Inspect all cellars and either fully prevent ingress; or provide functional egress from cellars by wildlife.

Date: 05/12/2020

Response: CA COMPLETED

Date of Completion: 05/08/2020

Operator Comment: Egress provided for cellars.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 138436

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.  
Properly dispose of oily waste in accordance with 907.e.

Date: 05/12/2020

Response: CA COMPLETED

Date of Completion: 04/29/2020

Operator  
Comment:

Tightened fitting on wellhead and cleaned up impacted soil.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aaron Axelson

Signed: \_\_\_\_\_

Title: Sr. Production Foreman

Date: 5/11/2020 3:59:09 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402395265	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files