

BP L48 San Juan



V2 Compliance Follow Up Form

18154395226

Reference Number:

20200909-18154395226

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com) | kenneth.canterbury@crossfire-llc.com

Submission Date:

Sep 9, 2020 10:24:37 AM MDT

Location:

2999 Co Rd 215, Durango, CO 81303, USA

Sep 9, 2020 10:19:33 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name	kenneth.canterbury@crossfire-llc.com
Date	Aug 25, 2020
Well Name	GEARHART GAS UNIT A 1
API Number	50670694400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Weed Debris

Photo of first corrective action completed



Completed work description Corrective
 Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2

Fixed erosion

Photo of third corrective action completed



Completed work description of corrective action 3

Installed rock run down

Photo of fourth corrective action completed



Completed work description

Cleaned up weeds

Completed work description of corrective action 4

Picked up trash

Summary of all work completed

Compliance, fixed erosion , installed rock run down and picked up trash