

Inspection Photos

Loc#323879

Operator: Caerus

Inspection Number: 692402500

Inspection Date: 9/11/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources





Photo#1:
Overview of area (approx. .25 acre) on South side of pad Location that has not been stabilized.

September 11, 2020



Photo#2:
View of area of Location That has not been stabilized.

September 11, 2020



Photo#3:
BMP repaired at access road.

September 11, 2020