

# Inspection Photos

API: 071-06397

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 9/11/2020



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06397 | Date: 9/11/2020

## Inspection Photos



**Photo 1.** Facing northeast toward the reclaimed access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06397 | Date: 9/11/2020



## Inspection Photos



**Photo 2.** Facing northeast along the former access road. The perennial vegetation has established along the reclaimed road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06397 | Date: 9/11/2020



## Inspection Photos



**Photo 3.** Facing north along the reclaimed road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06397 | Date: 9/11/2020



## Inspection Photos



**Photo 4.** Facing north toward the location. The vegetation has uniformly re-established at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06397 | Date: 9/11/2020



## Inspection Photos



**Photo 5.** Facing south toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06397 | Date: 9/11/2020