

Final Reclamation Inspection

September 10, 2020

Operator: MALLARD EXPLORATION LLC- #10670

Location ID: 455385

Inspection Document #: 697501975

Weld County, CO

NWNE Section 30 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Gadwall /Pad
Location ID: 455385



Photo 1. Photo taken north of the location, facing South. Photo illustrates location has not yet been constructed at the proposed well location based off field observations.