

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2020

Submitted Date:

09/14/2020

Document Number:

699102372**FIELD INSPECTION FORM**Loc ID 330392 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251213	WELL	PR	05/25/1999	OW	123-19016	GITTLEIN D #9-7	WK

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:  Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 251213 Type: WELL API Number: 123-19016 Status: PR Insp. Status: WK

**Cement**Cement ContractorContractor Name: SPN Well Services

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 6862Cement Volume (sx): 2

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment:

COGCC Inspection Report Summary  
 On Monday 9/14/20 at approximately 0833hrs, I, Inspector Adam Burns,  
 Conducted an on-site inspection at Gittlein D 9-7 of Noble Energy at  
 Location ID: 330392 in Weld County, Colorado.  
 Weather: Clear Sky  
 While there, I witnessed "SPN Well Services" RU Rocky SPN Well Services, RIH with  
 plug. Set CIBP #1 plug @6862' with 2 sacks of cmt on top. PSI Tested to 500 PSI for 15  
 min.  
 No violation of the COGCC rules were observed at the time of inspection.  
 This is a summary of inspection report.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102373	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246696">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246696</a>