

FORM  
INSPRev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/14/2020

Submitted Date:

09/14/2020

Document Number:

699102374

### FIELD INSPECTION FORM

Loc ID 330392 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251213	WELL	PR	05/25/1999	OW	123-19016	GITTLEIN D #9-7	WK

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 251213 Type: WELL API Number: 123-19016 Status: PR Insp. Status: WK

**Cement**

Cement Contractor

Contractor Name: SPN Well Services Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_ Circulate to Surface: \_\_\_\_\_  
 Cement Fall Back: \_\_\_\_\_ Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_ Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 6560 Cement Volume (sx): 2

Good Return During Job: \_\_\_\_\_ Cement Type: \_\_\_\_\_

Comment: [COGCC Inspection Report Summary](#)  
 On Monday 9/14/20 at approximately 1139hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Gittlein D 9-7 of Noble Energy at Location ID: 330392 in Weld County, Colorado.  
 Weather: Clear Sky  
 While there, I witnessed "SPN Well Services" RU Rocky SPN Well Services, RIH with plug. Set CIBP #2 plug @6560' with 2 sacks of cmt on top.  
 No violation of the COGCC rules were observed at the time of inspection.  
 This is a summary of inspection report.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102375	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246697">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5246697</a>