

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 334387



**New 2" stainless steel flowline installed from
wellhead to separators**

Inspection Photos
Operator Name: Caerus Piceance LLC
Facility ID: 334387



New 2" stainless steel dump line riser at separator



Old 3" carbon steel flowline abandoned and removed from location