

Inspection Photos
Location Name: BEVO /4-36M
Location #: 414138



Photo #1

Bevo 4-36 SWD (05-123-30585) UIC - Wellsite
Temporarily Abandoned | TA
Not Injecting – UIC Facility Abandoned



Photo #2

Bevo 4-36 SWD UIC – Wellhead
Locked-Out
Tbg. Press: Unavailable
Csg. Press: Unavailable
Bradenhead Press: Unavailable

Inspection Photos
Location Name: BEVO /4-36M
Location #: 414138



Photo 3

Bevo 4-36 SWD UIC - Disposal Facility

Temporarily Abandoned | TA

UIC Facility Abandoned

ALL Equipment removed

