

Final Reclamation Inspection

September 10, 2020

Operator: VERDAD RESOURCES LLC - #10651

Location ID: 423833

Inspection Document #: 697501987

Weld County, CO

SESE Section 11 T9N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Dietzler #1-11-9-60
Location ID: 423833



Photo 1. Photo taken from the eastern location, facing North. Photo illustrates Operator has performed final reclamation activities and has performed recent weed management.

Inspection Photos
Location Name: Dietzler #1-11-9-60
Location ID: 423833



Photo 2. Photo taken from the eastern location, facing Northwest. See comments under Photo 1.

Inspection Photos
Location Name: Dietzler #1-11-9-60
Location ID: 423833



Photo 3. Photo taken from the eastern location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: Dietzler #1-11-9-60
Location ID: 423833



Photo 4. Photo taken from the eastern location, facing Southwest. See comments under Photo 1.

Inspection Photos

Location Name: Dietzler #1-11-9-60

Location ID: 423833



Photo 5. Photo taken from a section of the location. Photo illustrates germination of desirable grass plant species.

Inspection Photos
Location Name: Dietzler #1-11-9-60
Location ID: 423833



Photo 6. Photo taken from the eastern location, facing North. Photo illustrates the location (left of the red-dashed line) and the adjacent reference area (right of the red-dashed line).