

Inspection Photos
Facility Name: BEVO 4-36 SWD /
Facility #: 159969



Photo #1

Bevo 4-36 SWD (05-123-30585) UIC - Wellsite
Temporarily Abandoned | TA
Not Injecting – UIC Facility Abandoned



Photo #2

Bevo 4-36 SWD UIC – Wellhead
Locked-Out
Tbg. Press: Unavailable
Csg. Press: Unavailable
Bradenhead Press: Unavailable

Inspection Photos
Facility Name: BEVO 4-36 SWD /
Facility #: 159969



Photo 3

Bevo 4-36 SWD UIC - Disposal Facility

Temporarily Abandoned | TA

UIC Facility Abandoned

ALL Equipment removed

