

Inspection Photos
Location Name: Anderson 22-32
Location ID: 328576



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Anderson 22-32
Location ID: 328576



Photo 3 WH appears to have a leak



Photo 4 WH appears to have a leak



Inspection Photos
Location Name: Anderson 22-32
Location ID: 328576




Photo 5 Braden head appears to have a leak from riser

Photo 6 Braden head appears to have a leak from riser.