

Inspection Photos

Loc#437712

Operator: SWN

Insp#: 692402480

Insp Date: 8/26/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

View up County road and turn out where access road diverts into Location.



Photo#2:

View off turnout and access road leading into Location.

August 26, 2020



Photo#3:
View along access road to Northeast.



Photo#4:
View along access road to Southwest.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

SWN North Hayden Loc#437712



Photo#5:

Overview of Location and access road leading from County road into compacted trafficked area.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

SWN North Hayden Loc#437712



Photo#6:
View of compacted trafficked area.

Photo#7:
View of compacted trafficked area.

August 26, 2020



Photo#8:

View from South end of Location to North. Canada Thistle in foreground.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

SWN North Hayden Loc#437712



Photo#9:
Erosion occurring at South end of site.



Photo#10:
Erosion occurring at South end of site.

August 26, 2020



Photo#11:
Vegetation, is not yet uniform and sparse in areas.



Photo#12:
Vegetation, is not yet uniform and sparse in areas.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

SWN North Hayden Loc#437712