

Inspection Photos
Location Name: Hill Ranch #25-05V
Location ID: 307995



Photo 1 Meter house



Photo 2 Stained soil at liquid ring

Inspection Photos
Location Name: Hill Ranch #25-05V
Location ID: 307995



Photo 3 Stained soil behind meter house



Photo 4 Same stain different view

Inspection Photos
Location Name: Hill Ranch #25-05V
Location ID: 307995



Photo 5 Pit / Has vegetation in pit needs to be removed



Photo 6 Drive head & engine skid