

Inspection Photos

API#107-06248

Operator: Bluestone

Insp#: 692402480

Insp Date: 8/26/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from Northeast corner to South, note thistle plants scattered down the slope. Insert is of access road that remains in place.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bluestone PA Pritlaw Partners API#107-06248



Photo#2:

While grasses are established., areas having more animal impact are infested with B List Noxious Weeds; Houndstongue, Musk and Bull thistle.

August 26, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Bluestone PA Pritlaw Partners API#107-06248



Photo#3:
Site fencing in disrepair.



Photo#4:
Site fencing in disrepair

August 26, 2020