



99999999

RADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

FACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

NOTICE OF SATISFACTORY INSPECTION

API No. 05-	025 - 2 09207	LEASE NAME:	Bloodspring
LOCATION:	SWSW 6-9N-53	OPERATOR:	Winflow
DATE:	4-8-96	INSPECTOR:	EBB \ Ed Binkley (970) 842-4465
Insp. Type:	SR	Insp. Status:	DA
PA:	Y	N	
Pass/Fail:	P	F	
Viol.:	Y	N	
NOV:	Y	N	

INSPECTION ITEM (RULE)	COMMENTS	INPUT
Well ID Signs (210)		
Pits (Reserve/Production)(904)		
Fences (604 C.(3), 1003 A.)		
Tank Battery Equipment(604)		
Fire Walls/Berms/Dikes(604)		
General Housekeeping (603g)		
Spills(Oil/Water)(907)		
Bradenhead (207)		
Drilling /Workover (315)		
Surface Rehabilitation (317)	grass land	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:



00269880

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission. Submit a copy or FAX to the inspector with date remedied and your signature. EBB fax is 970-842-4467.

White - File Green - Operator Canary - Well Site

APR 18 1996