

Inspection Photos

9/14/2020

Operator: BERRY PETROLEUM COMPANY LLC
- 10091

Location ID: 335981
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335981



Photo 1: Photo taken from the Location, facing northwest. Photo provides overview of the Location and reclamation in process.



Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335981



Photo 2: Photo taken from the Location, facing northeast. Photo provides overview of the Location and reclamation in process.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335981



Photo 3: Photo taken from the Location. Photo shows desiccated Mullien and thistle plants from initial weed management efforts.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335981



Photo 4: Photo shows example of Houndstongue rosette observed on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335981



Photo 5: Photo shows example of thistle rosette observed on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: BERRY PETROLEUM COMPANY LLC - 10091

Location ID: 335981



Photo 6: Photo shows example of thistle rosettes observed on the Location.

