

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2020

Submitted Date:

09/15/2020

Document Number:

699102386

**FIELD INSPECTION FORM**

Loc ID 459556 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459554	WELL	XX	12/05/2018		123-48943	Johnson C32-785	ND
459555	WELL	XX	12/05/2018		123-48944	Johnson C32-765	ND
459557	WELL	XX	12/05/2018		123-48945	Johnson C32-770	ND
459558	WELL	XX	12/05/2018		123-48946	Johnson C32-755	ND
459559	WELL	XX	12/05/2018		123-48947	Johnson C32-775	ND

**General Comment:**

[NO oil & gas activity](#)

**Inspected Facilities**

Facility ID: 459554 Type: WELL API Number: 123-48943 Status: XX Insp. Status: ND

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459555 Type: WELL API Number: 123-48944 Status: XX Insp. Status: ND

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459557 Type: WELL API Number: 123-48945 Status: XX Insp. Status: ND

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459558 Type: WELL API Number: 123-48946 Status: XX Insp. Status: ND

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 459559 Type: WELL API Number: 123-48947 Status: XX Insp. Status: ND

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: ND

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 9/15/20 at approximately 1055hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Johnson C29-04 Pad of Noble Energy at Location ID: 459556 in Weld County, Colorado.                      Weather: Sunny and Dry.                      While there, I observed a location that is currently not drilled "no oil &amp; gas activity".                      No violation of the COGCC rules were observed at the time of inspection.                      This is a summary of inspection report.</p>	burnsa	09/15/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102387	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247451">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247451</a>