

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/15/2020

Submitted Date:

09/15/2020

Document Number:

699102388**FIELD INSPECTION FORM**Loc ID 460293 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
460291	WELL	XX	12/21/2018		123-49291	Johnson C32-725	ND
460292	WELL	XX	12/21/2018		123-49292	Johnson C32-745	ND
460294	WELL	XX	12/21/2018		123-49293	Johnson C32-730	ND
460295	WELL	XX	12/21/2018		123-49294	Johnson C32-715	ND
460296	WELL	XX	12/21/2018		123-49295	Johnson C32-735	ND

General Comment:[No oil & gas activity.](#)

Inspected Facilities

Facility ID: 460291 Type: WELL API Number: 123-49291 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: ND

Corrective Action: _____ Date: _____

Facility ID: 460292 Type: WELL API Number: 123-49292 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: ND

Corrective Action: _____ Date: _____

Facility ID: 460294 Type: WELL API Number: 123-49293 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: ND

Corrective Action: _____ Date: _____

Facility ID: 460295 Type: WELL API Number: 123-49294 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: ND

Corrective Action: _____ Date: _____

Facility ID: 460296 Type: WELL API Number: 123-49295 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: ND

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 9/15/20 at approximately 1111hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Johnson C29-03 Pad of Noble Energy at Location ID: 460293 in Weld County, Colorado.</p> <p>Weather: Sunny and Dry.</p> <p>While there, I observed a location that is currently not drilled "no oil & gas activity".</p> <p>No violation of the COGCC rules were observed at the time of inspection.</p> <p>This is a summary of inspection report.</p>	burnsa	09/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102389	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247452