



99999999

RADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

NOTICE OF UNSATISFACTORY INSPECTION

NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 075 - 07546	LEASE NAME: State 1				
LOCATION: NE SW 6 - 9N - 53W	OPERATOR: HLM				
DATE: 4-8-96	INSPECTOR: EBB \ Ed Binkley (970) 842-4465				
Insp. Type: SR	Insp. Status: DIA	PA: <input checked="" type="radio"/> Y <input type="radio"/> N	Pass/Fail: <input checked="" type="radio"/> P <input type="radio"/> F	Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM (RULE)	COMMENTS	INPUT
Well ID Signs (210)		
Pits (Reserve/Production)(904)		
Fences (604 C.(3), 1003 A.)		
Tank Battery Equipment(604)		
Fire Walls/Berms/Dikes(604)		
General Housekeeping (603g)	(C)	
Spills(Oil/Water)(907)		
Bradenhead (207)		
Drilling /Workover (315)		
Surface Rehabilitation (317)	grassland	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:



00269869

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission. Submit a copy or FAX to the inspector with date remedied and your signature. EBB fax is 970-842-4467.

White - File Green - Operator Canary - Well Site

APR 18 1996