

Inspection Photos
Location Name: Johnson 62N68W 12SEW
Location ID: 336430



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Johnson 62N68W 12SENW
Location ID: 336430



Photo 3 WH sign

Photo 4 WH

Inspection Photos
Location Name: Johnson 62N68W 12SE/W
Location ID: 336430



Photo 5 WH sign

Photo 6 WH

Inspection Photos
Location Name: Johnson 62N68W 12SEW
Location ID: 336430



Photo 7 TB sign

Photo 8 TB

Inspection Photos
Location Name: Johnson 62N68W 12SEW
Location ID: 336430



Photo 9 Flow lines

Photo 10 Horizontal Heated Separator

Inspection Photos
Location Name: Johnson 62N68W 12SEW
Location ID: 336430



Colorado Oil & Gas Conservation Commission
Longmont, CO 80504, USA
40.15633, -104.95525, 4810.9ft, 166°
09/15/2020 12:41:34

Photo 13 ECD