

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/14/2020

Submitted Date:

09/14/2020

Document Number:

700701543**FIELD INSPECTION FORM**
 Loc ID 335354 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| , Caerus | | COGCC.inspections@caerus oilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 264878 | WELL | PR | 02/23/2003 | GW | 045-08955 | BENZEL 36-2D (B36X) | PR |
| 264879 | WELL | PR | 02/19/2003 | GW | 045-08956 | BENZEL 36-2C (B36X) | PR |
| 264880 | WELL | PR | 02/27/2003 | GW | 045-08957 | BENZEL 36-1B (B36X) | PR |
| 264887 | WELL | PR | 02/19/2003 | GW | 045-08963 | BENZEL 36-7B (B36X) | PR |

General Comment:**COGCC Inspection Report Summary**

On Monday 9/14/20 at approximately 1330, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus B36X, at Location # 335354 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

This is a summary of inspection report.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|-----|-------|--|
| Comment: | 911 | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|--------|-------|--|
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------------------|-----|-------|-----------------|
| Type: Bird Protectors | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------------|---|-------|
| Type: Gas Meter Run | # 5 | |
| Comment: | All meters have been calibrated on location within the past year. | |
| Corrective Action: | | Date: |
| Type: Deadman # & Marked | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| METHANOL | 1 | 1000 GAL | STEEL AST | | , |
| Comment: | shared containment with condensate tanks | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 2 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | |
|-----------------------|------------|-----------------------|------------|------------------|
| Facility ID: 264878 | Type: WELL | API Number: 045-08955 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | producing | | | |
| Corrective Action: | | | Date: | |
| | | | | |
| Facility ID: 264879 | Type: WELL | API Number: 045-08956 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | producing | | | |
| Corrective Action: | | | Date: | |
| | | | | |
| Facility ID: 264880 | Type: WELL | API Number: 045-08957 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | producing | | | |
| Corrective Action: | | | Date: | |
| | | | | |
| Facility ID: 264887 | Type: WELL | API Number: 045-08963 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | producing | | | |
| Corrective Action: | | | Date: | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | | Ditches | | | | |
| | | Culverts | | | | |
| | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 700701554 | Photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5247973 |