

Inspection Photos
Location Name: AC 17-13
Location ID: 307376



Photo 1 location sign. Unused equipment well has been TA for an extended period of time.



Photo 2 unused not LOTO riser

Inspection Photos
Location Name: AC 17-13
Location ID: 307376



Photo 3 Well is TA. Risers not LOTO. Unused equipment risers and electric equipment. Weeds on location.



Photo 4 Trash; old pipeline marker.