

Inspection Photos
Location Name: Razor 27L PAD
Location ID: 430313



Photo 1 – Pad Signage at Entrance



Photo 2 – Heater Treaters, Flare



Inspection Photos
Location Name: Razor 27L PAD
Location ID: 430313



Photo 3 – Tank Battery



Photo 4 – 3414H Wellhead, Stained Soil

Inspection Photos
Location Name: Razor 27L PAD
Location ID: 430313



Photo 5 – 3404B Wellhead, Stained Soil



Photo 4 – 3403B Wellhead, Stained Soil