



40.18914, -107.93009, 8156.7ft, 346°
09/14/2020 03:14:02 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Separator.

Wilson Creek 66

API: 05-103-09127

Inspection: 700403419



40.1891, -107.92994, 8160.2ft, 10°
09/14/2020 03:15:55 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Chemical & tank.

Wilson Creek 66

API: 05-103-09127

Inspection: 700403419



40.1891, -107.92994, 8160.2ft, 341°
09/14/2020 03:17:28 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Building & separator.

Wilson Creek 66

API: 05-103-09127

Inspection: 700403419