

## Inspection Photos

Location Name: GOLDEN EAGLE 30-05

API#: 05-071-09205

INSP. #: 695103273



Colorado Oil & Gas Conservation Commission  
37.14512, -104.93452, 2207.0m, 247°  
2020/09/11 08:25:22

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission  
37.14516, -104.93452, 2214.0m, 274°  
2020/09/11 08:26:32

PHOTO 2: WELL SIGN



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: GOLDEN EAGLE 30-05

API#: 05-071-09205

INSP. #: 695103273



**PHOTO 3: A WHOLE NEAR DRAIN OF COMPRESSOR SKID IS FULL OF WHAT APPEARS TO BE ENGINE OR COMPRESSOR OIL. Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. CA DATE 9/13/20.**



**PHOTO 4: ANOTHER IMAGE OF OILY FLUID RUNNING OUT OF COMPRESSOR SKID. FOLLOW CORRECTIVE ACTION GUIDANCE FROM PHOTO 3.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: GOLDEN EAGLE 30-05

API#: 05-071-09205

INSP. #: 695103273



Colorado Oil & Gas Conservation Commission  
37.14526, -104.9348, 2209.0m, 210°  
2020/09/11 08:29:24



Colorado Oil & Gas Conservation Commission  
37.14526, -104.9348, 2209.0m, 211°  
2020/09/11 08:30:21

**PHOTO 5: ANOTHER IMAGE OF OILY FLUID RUNNING OUT OF COMPRESSOR SKID AND IMPACTED OIL AROUND WEST SIDE OF SKID. FOLLOW CORRECTIVE ACTION GUIDANCE FROM PHOTO 3.**

**PHOTO 6: UNUSED EQUIPMENT STORED ON LOCATION (TBG SKID). COMPLY WITH RULE 603.f. CA DATE 10/11/20.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: GOLDEN EAGLE 30-05

API#: 05-071-09205

INSP. #: 695103273



**PHOTO 7: UNUSED EQUIPMENT STORED ON LOCATION.**  
**COMPLY WITH RULE 603.f. CA DATE 10/11/20.**

**PHOTO 8: UNUSED EQUIPMENT STORED ON LOCATION.**  
**COMPLY WITH RULE 603.f. CA DATE 10/11/20.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: GOLDEN EAGLE 30-05

API#: 05-071-09205

INSP. #: 695103273



**PHOTO 9: TRASH OF THE EAST SIDE OF ROW (PIECE OF OLD TUBING). COMPLY WITH RULE 603.f. CA DATE 10/11/20.**