

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06483**  
**Date: 9/11/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project northwestern corner facing southward.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area vegetation comprised of sagebrush and saltbush shrubland, with grasses and forbs such as western wheatgrass and snakeweed in the understory.