

Final Reclamation Inspection

September 15, 2020

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 317487

Inspection Document #: 697501993

Weld County, CO

SENW Section 36 T2N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE #36-1
Location ID: 317487




Photo 1. COGCC GISOnline aerial imagery from 2017 illustrating active operations. Aerial imagery is being used to illustrate the portion of the access road that had not been properly reclaimed. This inspection confirms the Operator performed the previous corrective actions.



Photo 2. Photo taken from the eastern access road, facing West. Photo illustrates Operator has performed final reclamation activities. However, crop establishment is not reflective of reference areas and will remain in-process.

Inspection Photos
Location Name: STATE #36-1
Location ID: 317487



Photo 3. Photo taken from the central access road, facing West. See comments under Photo 2.

Inspection Photos
Location Name: STATE #36-1
Location ID: 317487



Photo 4. Photo taken from the western access road, facing South. See comments under Photo 2.



Photo 5. Photo taken from the western access road, facing South. Photo illustrates Operator has removed all equipment.