

# Final Reclamation Inspection

September 15, 2020

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 318163

Inspection Document #: 697501995

Weld County, CO

NWSW Section 30 T2N R62W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SHOENEMAN #13-30  
Location ID: 318163



**Photo 1.** Photo taken from the well location/well location access road, facing North. Photo illustrates crop has already been harvested; however, successful establishment of crop growth (two-years in-a-row) appears reflective of reference crop areas.

Inspection Photos  
Location Name: SHOENEMAN #13-30  
Location ID: 318163



**Photo 2.** Photo taken from the tank battery location, facing North. Photo illustrates Operator has removed the equipment and crops have successfully established.

Inspection Photos  
Location Name: SHOENEMAN #13-30  
Location ID: 318163



**Photo 3.** Reference photo taken from the tank battery location, facing East. See comments under Photos 1 and 2.