

Inspection Photos
Location Name: Rasmussen #3
Location ID: 333145



Photo 1 WH sign

Photo 2 weeds overgrown around WH

Inspection Photos
Location Name: Rasmussen #3
Location ID: 333145



Photo 3 weeds overgrown along well access



Photo 4 weeds overgrown around WH

Inspection Photos
Location Name: Rasmussen #3
Location ID: 333145



Photo 5 weeds overgrown around wellsite