

Inspection Photos
Location Name: Jillson-East Rinn Facilities 22H-N268
Location ID: 434178



Colorado Oil & Gas Conservation Commission
8284 Co Rd 7, Longmont, CO 80504, USA
40.12005, -104.99434, 4897.8ft, 307
09/16/2020 15:01:59



Colorado Oil & Gas Conservation Commission
8284 Co Rd 7, Longmont, CO 80504, USA
40.12005, -104.99427, 4897.9ft, 307
09/16/2020 15:02:10

Photo 1 TB sign

Photo 2 TB

Inspection Photos
Location Name: Jillson-East Rinn Facilities 22H-N268
Location ID: 434178



Photo 3 Horizontal Heated Separators

Photo 4 ECDs

Inspection Photos
Location Name: Jillson-East Rinn Facilities 22H-N268
Location ID: 434178



Photo 5 Vertical Separator

Photo 6 Gas Meter Run/Pig station

Inspection Photos

Location Name: Jillson-East Rinn Facilities 22H-N268

Location ID: 434178



Photo 7 Cards in meter house indicate current calibration