

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/16/2020

Submitted Date:

09/17/2020

Document Number:

701100357

**FIELD INSPECTION FORM**
 Loc ID 335652 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265443	WELL	SI	10/01/2018	GW	045-09015	CHEVRON 32-7D	SI
265530	WELL	PR	03/01/2019	GW	045-09026	CHEVRON 42-7D	PR
265531	WELL	PR	03/01/2019	GW	045-09025	CHEVRON 43-7D	PR
265532	WELL	PR	03/01/2019	GW	045-09024	CHEVRON 31-7D	PR
265533	WELL	PR	03/01/2019	GW	045-09023	CHEVRON 41-7D	PR
265534	WELL	PR	03/01/2019	GW	045-09022	CHEVRON 33-7D	PR
288551	WELL	PR	03/01/2019	GW	045-13296	CHEVRON 41A-7D	PR
289254	WELL	PR	03/01/2019	GW	045-13708	CHEVRON 41C-7D	PR
289376	WELL	PR	03/01/2019	GW	045-13738	CHEVRON 41D-7D	PR
289422	WELL	PR	03/01/2019	GW	045-13759	CHEVRON 42A-7D	PR
289423	WELL	PR	03/01/2019	GW	045-13758	CHEVRON 31B-7D	PR
289424	WELL	PR	03/01/2019	GW	045-13757	CHEVRON 43B-7D	PR
289425	WELL	PR	06/01/2020	GW	045-13756	CHEVRON 43D-7D	PR
289426	WELL	PR	03/01/2019	GW	045-13755	CHEVRON 43A-7D	PR
289699	WELL	PR	03/01/2019	GW	045-13851	CHEVRON 42D-7D	PR
289700	WELL	PR	03/01/2019	GW	045-13850	CHEVRON 31D-7D	PR

**General Comment:**

**Location****Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 265443 Type: WELL API Number: 045-09015 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Facility ID: 265530 Type: WELL API Number: 045-09026 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:  Date:

Facility ID: 265531 Type: WELL API Number: 045-09025 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:  Date:

Facility ID: 265532 Type: WELL API Number: 045-09024 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:  Date:

Facility ID: 265533 Type: WELL API Number: 045-09023 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:  Date:

Facility ID: 265534 Type: WELL API Number: 045-09022 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:  Date:

Facility ID: 288551 Type: WELL API Number: 045-13296 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Corrective Action:  Date:

Facility ID: 289254 Type: WELL API Number: 045-13708 Status: PR Insp. Status: PR

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289376 Type: WELL API Number: 045-13738 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289422 Type: WELL API Number: 045-13759 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289423 Type: WELL API Number: 045-13758 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289424 Type: WELL API Number: 045-13757 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289425 Type: WELL API Number: 045-13756 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289426 Type: WELL API Number: 045-13755 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289699 Type: WELL API Number: 045-13851 Status: PR Insp. Status: PR				
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 289700 Type: WELL API Number: 045-13850 Status: PR Insp. Status: PR				

<b>Producing Well</b>			
Comment:	Producing well		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Compaction	Pass			
Ditches	Pass					
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701100361	Inspection 701100357 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249800">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5249800</a>