

Inspection Photos
Location Name: Peoc-NVG 41-23H
Location ID: 316766



Photo 1. Overview of location taken facing north.



Photo 2. Stained soil at wellhead.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Peoc-NVG 41-23H
Location ID: 316766



Photo 3. Stained soil at pump jack motor.



Photo 4. Stained soil from tank overflow and at loadout.

Inspection Photos
Location Name: Peoc-NVG 41-23H
Location ID: 316766



Photo 5. Close up of soil staining at loadout.



Photo 6. Close up of stained soil from tank overflow.



Inspection Photos
Location Name: Peoc-NVG 41-23H
Location ID: 316766



Photo 7. Close up of soil staining at loadout.



Photo 8. Close up of soil staining at loadout.



Inspection Photos
Location Name: Peoc-NVG 41-23H
Location ID: 316766



Photo 9. Stained soil and noxious weeds at tank battery berm.



Photo 10. Gravel stored on location.

