

Inspection Photos
Location Name: Routt Bonanza 1-22
Location ID: 316756



**Photo 1. Overview of location taken facing southeast.
Equipment stored on location.**



Inspection Photos
Location Name: Routt Bonanza 1-22
Location ID: 316756



Photo 2. Example of stained soil on location.



Photo 3. Example of stained soil on location.

Inspection Photos
Location Name: Routt Bonanza 1-22
Location ID: 316756



Photo 4. Example of stained soil on location.



Photo 5. Example of tank labels tearing/fading.

Inspection Photos
Location Name: Routt Bonanza 1-22
Location ID: 316756



Photo 6. Example of tank labels tearing/fading. Weeds.



Photo 7. Weeds on location. Truck stored on location.